

Daily Work History

(By Location)

Period: 2/1/2010 - 2/28/2010

Work: All categories and types

Location: All locations in all areas

Assignment: Precinct 1

Hill County

Precinct 1: County Roads

| Location | Date | Work Done |
|--|-----------|---|
| Cedar Crest Ln | 2/16/2010 | Trimmed brush or trees |
| Easy Ln | 2/18/2010 | Bladed surface; Added rock |
| Horseshoe Ln | 2/18/2010 | Trimmed brush or trees |
| Jill Pill between Bob White Dr and Marcy Dr | 2/22/2010 | Bladed surface; Added rock |
| | 2/22/2010 | Bladed surface; Added rock oversize on HCR 1150 |
| Junip Pk Rd One | 2/19/2010 | Trimmed brush or trees |
| Lakeshore Tr between Post Oak Dr /LOR and Park Ave | 2/24/2010 | Trimmed brush or trees |
| Lakeview Dr E | 2/18/2010 | Trimmed brush or trees |
| Leasure Ln | 2/17/2010 | Bladed surface; Added rock |
| Palomino Lp | 2/25/2010 | Trimmed brush or trees |
| Park Ave | 2/24/2010 | Cleared debris or fallen tree |
| Quail Lake E at/near Quail Lake W | 2/19/2010 | Bladed surface; Added rock |
| Timberline Dr | 2/22/2010 | Cleared debris or fallen tree |
| HCR 1104 LP | 2/16/2010 | Trimmed brush or trees |
| | 2/17/2010 | Trimmed brush or trees |
| HCR 1106 at/near HCR 1114 | 2/10/2010 | Set road drainage culvert lbstalled 2 horns on HCR 1106 & 1114 |
| HCR 1145 LP | 2/10/2010 | Hauled materials for work crew hauled 5 loads of base |
| | 2/10/2010 | Hauled materials for work crew hauled 4 loads of base and 2 loads of over sized |
| | 2/15/2010 | Hauled materials for work crew |
| HCR 1150 | 2/24/2010 | Hauled materials for work crew hauled 4 loads of base & 2 loads of over-size |
| | 2/26/2010 | Hauled materials for work crew hauled 7 loads of base |
| HCR 1150 at/near HCR 1153 | 2/22/2010 | Set road drainage culvert kauled 5 loads of gravel for road base |

Daily Work History

(By Location)

Period: 2/1/2010 - 2/28/2010

Work: All categories and types

Location: All locations in all areas

Assignment: Precinct 1

Hill County

Precinct 1: County Roads

| | | |
|---|-----------|--|
| HCR 1150 at/near HCR 1314 | 2/26/2010 | Hauled materials for work crew hauled 3 loads to 1150;1 load to 1303 ;2 loads to 1314 |
| HCR 1150 at/near HCR 1405 | 2/25/2010 | Hauled materials for work crew hauled 5 loads of base and 1 load of #3 rock |
| HCR 1153 at/near HCR 1150 | 2/22/2010 | Set road drainage culvert replaced culvertsd on 1150 & 1153 |
| HCR 1201 between HCR 1206 and HCR 1153 | 2/2/2010 | Bladed surface; Added rock |
| HCR 1207 | 2/3/2010 | Bladed surface; Added rock |
| HCR 1211 between Quail Lake E and HCR 1413 E | 2/24/2010 | Overlaid road with asphalt hauled 4 loads of base to 1211,1 load to Quall lake E; 1 load to 1413 |
| HCR 1212 | 2/1/2010 | Bladed surface; Added rock |
| | 2/17/2010 | Bladed surface; Added rock |
| HCR 1212 at/near HCR 1206 | 2/19/2010 | Hauled materials for work crew |
| HCR 1217 | 2/25/2010 | Bladed surface; Added rock Bladed 1159,1446,1300, |
| HCR 1227 | 2/18/2010 | Cleared debris or fallen tree repaired chipper;changed fuel pump |
| HCR 1241 between Quail Lake W and Pleasant Dr graded Leasure Lane & Easy Lane | 2/16/2010 | Bladed surface; Added rock |
| HCR 1258 at/near HCR 1263 | 2/3/2010 | Bladed surface; Added rock replasced batteries on Volvo motor grader |
| HCR 1263 | 2/2/2010 | Hauled materials for work crew hauled 4 loads of base |
| | 2/3/2010 | Hauled materials for work crew Huled 4 loads of base; |
| HCR 1263 between HCR 1258 and HCR 1258 | 2/1/2010 | Hauled materials for work crew hauled 4 loads of base;helped replace batteries on Volvo |
| HCR 1300 at/near HCR 1223 | 2/26/2010 | Bladed surface; Added rock |
| HCR 1300 between HCR 1300 and HCR 1223 | 2/26/2010 | Bladed surface; Added rock |
| HCR 1405 between HCR 1150 and HCR 1212 Bladed creekwood & 1253 | 2/26/2010 | Bladed surface; Added rock |
| HCR 1413 E | 2/16/2010 | Set road drainage culvert set culverts on 1413 & 1258 |

Daily Work History

(By Location)

Period: 2/1/2010 - 2/28/2010

Work: All categories and types

Location: All locations in all areas

Assignment: Precinct 1

Hill County

Precinct 1: County Roads

| | | |
|------------------------------|-----------|--|
| HCR 1413 W | 2/16/2010 | Cleaned out or fixed road culvert replaced a horn on HCR 1258 |
| | 2/18/2010 | Replaced road culvert added extension on horn on 1413 |
| | 2/18/2010 | Replaced road culvert put rock & road base on low water crossing on 1137 |
| <hr/> | | |
| HCR 1414 | 2/1/2010 | Bladed surface; Added rock |
| <hr/> | | |
| HCR 1414 at/near HCR 1413 W | 2/26/2010 | Bladed surface; Added rock need rock on 1414 |
| <hr/> | | |
| HCR 1425 | 2/9/2010 | Hauled materials for work crew hauled 2 loads of over sized and 1 load of base; repaired rear tire |
| | 2/9/2010 | Overlaid road with asphalt hauled 2 loads of over-sized & 2 loads of base |
| <hr/> | | |
| HCR 1425 at/near HCR 1145 LP | 2/9/2010 | Bladed surface; Added rock |
| <hr/> | | |
| HCR 1429 at/near HCR 1413 W | 2/27/2010 | Bladed surface |
| <hr/> | | |
| HCR 1432 | 2/2/2010 | Bladed surface; Added rock |
| <hr/> | | |
| HCR 1432 at/near HCR 1130 N | 2/4/2010 | Hauled materials for work crew |
| <hr/> | | |
| HCR 1458 at/near HCR 1137 | 2/2/2010 | Hauled materials for work crew |

County: Other Class: Other Type

| Location | Date | Work Done |
|------------------------|----------|-------------------------|
| (location not on list) | 2/2/2010 | Worked at precinct barn |