

Daily Work History

(By Location)

Period: 6/1/2010 - 6/30/2010

Work: All categories and types

Location: All locations in all areas

Assignment: All

Hill County

Precinct 1: County Roads

| Location | Date | Work Done |
|---------------------|-----------|---|
| Cedar Creek Park Rd | 6/22/2010 | Bladed surface hauled water to 1231 |
| | 6/23/2010 | Bladed surface watered the surface to reduce the dust |
| Cedar St /LOR | 6/17/2010 | Patched road surface moved backhoe to EOG well site for gravel;EOG donated gravel for road repair |
| Deer Shadow Cir | 6/10/2010 | inspected HCR 1300,1413,purchased filters for equipment,check motor grader for hydrolic leaks:Met with MrsHadden to ditch work on Deer Shadow |
| T St | 6/9/2010 | Cleaned outfall ditch cleared Water way on 1212 |
| Washita Tr | 6/29/2010 | Patched road surface Moved equipment to barn for repairs;ditch work on 1321 |
| Waterview Dr | 6/30/2010 | Cleared debris or fallen tree graveled Wachitaw;Creekwood;repaired equipment |
| HCR 1125 | 6/29/2010 | Worked at precinct barn installed a shoot on back of Volvo to accomadate the pot hole patcher |
| HCR 1127 | 6/24/2010 | Hauled materials for work crew hauled surplus rock to yard for storage |
| | 6/24/2010 | Overlaid road with asphalt hauled base from EOG site-3 loads stock piled at barn |
| HCR 1145 LP | 6/1/2010 | Overlaid road with asphalt hauled 7 loads of base |
| | 6/1/2010 | Bladed surface; Added rock |
| | 6/2/2010 | Bladed surface; Added rock graded roads in Blum as part of the interlocal agreement |
| | 6/9/2010 | Bladed surface; Added rock added 2 loads of base |
| | 6/11/2010 | Bladed surface; Added rock |
| HCR 1212 | 6/2/2010 | hauled horns for replacement of 1212.Called dig test for locates on phone and gas lines |
| | 6/4/2010 | Hauled materials for work crew hauled load of flex base to HCR 1212 |

Daily Work History

(By Location)

Period: 6/1/2010 - 6/30/2010

Work: All categories and types

Location: All locations in all areas

Assignment: All

Hill County

Precinct 1: County Roads

| | | |
|--|-----------|--|
| HCR 1212 | 6/4/2010 | Replaced road culvert installed two new horns on 1212 where it joins FM 3050 |
| | 6/4/2010 | Hauled materials for work crew hauled 2 loads(47 tons) of base |
| | 6/7/2010 | Hauled materials for work crew hauled 2 loads of over-size and 2 loads of base |
| | 6/7/2010 | Bladed surface; Added rock assisted in running the bmag. |
| | 6/7/2010 | Hauled materials for work crew hauled 3 loads of flex base and 3 loads of over-size rock |
| | 6/8/2010 | Bladed surface; Added rock raised the level of 1212 over new culverts;watered and rolled road base |
| | 6/8/2010 | Hauled materials for work crew hauled water to 1212 to pack base;put silt fence around horns on 1212 |
| | 6/8/2010 | Hauled materials for work crew hauled 2 loadsw of base;moved roller over to HCR 1212. |
| HCR 1231 | 6/18/2010 | Hauled materials for work crew hauled 8 loads of base out of EOG welllls ite for road construction on 1231 |
| | 6/18/2010 | Hauled materials for work crew Drove motorgrasder to smooth road base;hauled 9 loads |
| HCR 1231 between HCR 1230 and HCR 1221 | 6/21/2010 | Bladed surface; Pulled shoulders or ditches |
| HCR 1236 | 6/24/2010 | Hauled materials for work crew hauled rock from EOG well site to Pct. Barn for storage of surplus rock |
| | 6/24/2010 | Hauled materials for work crew |
| | 6/24/2010 | Hauled materials for work crew loaded trucks from EOG site for HCR 1321 |
| | 6/28/2010 | Hauled materials for work crew loaded trucks from EOG site |
| HCR 1236 at/near Cedar Creek Park Rd | 6/23/2010 | Bladed surface watered road to settle dust |
| HCR 1245 between HCR 1240 and HCR 1250 | 6/1/2010 | Mowed grass mowed 1256; |
| HCR 1300 | 6/28/2010 | Hauled materials for work crew hauled 6 loads of base;5 to 1300;1 to yard |

Daily Work History

(By Location)

Period: 6/1/2010 - 6/30/2010

Work: All categories and types

Location: All locations in all areas

Assignment: All

Hill County

Precinct 1: County Roads

| | | |
|---------------------------|---|--|
| HCR 1300 | 6/28/2010 | Hauled materials for work crew hauled 5 loads of base |
| | 6/28/2010 | Trimmed brush or trees |
| HCR 1303 | 6/29/2010 | Trimmed brush or trees sharpened cutter blades;reset boom pin |
| HCR 1321 | 6/23/2010 | Hauled materials for work crew hauled 6 loads of rock. |
| | 6/23/2010 | Hauled materials for work crew hauled |
| | 6/24/2010 | Hauled materials for work crew hauled 4 loads of base |
| | 6/24/2010 | Bladed surface; Pulled shoulders or ditches |
| | 6/29/2010 | Hauled materials for work crew 4 loads from EOG site |
| HCR 1321 at/near HCR 1300 | 6/28/2010 | Bladed surface; Added rock |
| HCR 1322 | 6/14/2010 | Bladed surface; Added rock Bvladed 13125,added rock |
| HCR 1413 E | 6/15/2010 | Bladed surface; Added rock bladed 6 loads of base into 1413 |
| HCR 1413 W | 6/14/2010 | Bladed surface; Pulled shoulders or ditches |
| | 6/14/2010 | Hauled materials for work crew hauled 4 loads of over-sized rock |
| | 6/14/2010 | Hauled materials for work crew hauled 4 loads of over-sized rock to 1413 |
| | 6/15/2010 | Bladed surface; Added rock |
| | 6/15/2010 | Bladed surface; Pulled shoulders or ditches |
| | 6/15/2010 | Hauled materials for work crew hauled 6 loads of over-sized rock |
| | 6/16/2010 | Hauled materials for work crew hauled 7 loads of base |
| | 6/16/2010 | Hauled materials for work crew |
| | 6/16/2010 | Bladed surface; Added rock |
| | 6/16/2010 | Hauled materials for work crew hauled 5 loads of base |
| | 6/17/2010 | Overlaid road with asphalt hauled 3 loads of over-sized rock:5 loads of base |
| 6/17/2010 | Bladed surface; Added rock | |
| 6/17/2010 | Hauled materials for work crew hauled 3 loads of base | |
| 6/17/2010 | Hauled materials for work crew hauled 7 loads of base | |

Daily Work History

(By Location)

Period: 6/1/2010 - 6/30/2010

Work: All categories and types

Location: All locations in all areas

Assignment: All

Hill County

Precinct 1: County Roads

| | | |
|------------------------------|-----------|--|
| HCR 1413 W | 6/17/2010 | Hauled materials for work crew hauled over-sized rock-6 loads |
| | 6/21/2010 | Hauled materials for work crew hauled 6 loads;2-mixed and 4 loads of #1 base |
| | 6/21/2010 | Hauled materials for work crew hauled 2 loads from EOG site;5 loads from Arnolds |
| HCR 1413 W at/near HCR 1321 | 6/21/2010 | Hauled materials for work crew hauled 3 loads of and 1 load of over-size |
| HCR 1418 | 6/14/2010 | Bladed surface; Added rock |
| HCR 1439 | 6/9/2010 | Bladed surface; Added rock added 3 loads of base |
| | 6/10/2010 | Hauled materials for work crew hauled 5 loads of base to HCR 1439 |
| | 6/10/2010 | Bladed surface; Added rock added 5 loads of base |
| HCR 1439 at/near HCR 1145 LP | 6/9/2010 | Hauled materials for work crew hauled 5 loads of base |
| HCR 1444 | 6/2/2010 | Trimmed brush or trees Inmates trimmed and cleared trees on HCR 1444 |

County: Other Class: Other Type

| Location | Date | Work Done |
|------------------------|-----------|--|
| (location not on list) | 6/3/2010 | Bladed surface; Added rock graded roads in Blum as part of the counties interlocal agreement with Blum. |
| | 6/3/2010 | Worked at precinct barn Repaired county equipment;moved equipment to next job site |
| | 6/7/2010 | Worked at precinct barn repaired county equipment;moved equipment to new work site |
| | 6/29/2010 | Worked at precinct barn repairedf flat;checked out HCR 1413,1300 & 1321.Assisted John Miller is picking up a dump site |
| | 6/30/2010 | Worked at precinct barn repaired equipment. Built a shoot for gravel attachment on dump truck. Repaired equipment. |