

Daily Work History (by Work Location)

Period: 2/1/2012 - 2/29/2012

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Hill County

Precinct 1: County Roads

Location	Date	Work Done
Live Oak Dr between Chisholm Pass and Country Club Rd	2/21/2012	Patched road surface
HCR 1120 between HCR 1414 and HCR 1120	2/2/2012	Hauled materials for work crew
	2/3/2012	Hauled materials for work crew hauled 2 loads to 1414;2 loads to 1120
	2/7/2012	Hauled materials for work crew hauled 3 loads to 1414;2 loads to 1302;1 load to 1120
HCR 1201	2/15/2012	Hauled materials for work crew placed large rap in right of way to patch washout
HCR 1207 between HCR 1207 and HCR 1212	2/1/2012	Bladed surface; Added rock
	2/1/2012	Bladed surface; Added rock Graded 1303 to 1314
HCR 1212	2/10/2012	Bladed surface; Pulled shoulders or ditches
	2/16/2012	Hauled materials for work crew 6 loads of base on 1212 North of 1207
	2/16/2012	Hauled materials for work crew hauled 6 loads of base
	2/24/2012	Hauled materials for work crew hauled 6 loads of base
	2/24/2012	Hauled materials for work crew
HCR 1212 between HCR 1212 and HCR 1231	2/14/2012	Hauled materials for work crew
HCR 1212 between HCR 1231 and HCR 1212	2/14/2012	Hauled materials for work crew hauled 2 loads of base to 1212;2 loads to 1231
HCR 1216	2/3/2012	Trimmed brush or trees
HCR 1217	2/3/2012	Trimmed brush or trees
HCR 1236 between HCR 1231 and HCR 1236	2/13/2012	Bladed surface; Added rock graded 1231 E and added rock
HCR 1240 between HCR 1240 and HCR 1246	2/14/2012	Bladed surface; Added rock
HCR 1248	2/15/2012	Bladed surface; Added rock
HCR 1263 between HCR 1258 and HCR 1263	2/16/2012	Bladed surface; Added rock
HCR 1300	2/9/2012	Hauled materials for work crew hauled 5 loads of base
HCR 1306	2/2/2012	Bladed surface; Pulled shoulders or ditches

Daily Work History (by Work Location)

Period: 2/1/2012 - 2/29/2012

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Hill County

Precinct 1: County Roads

HCR 1306	2/6/2012	Hauled materials for work crew
HCR 1306 at/near HCR 1120	2/6/2012	Hauled materials for work crew hauled 2 loads ; 1 load to 1120
HCR 1357	2/29/2012	Bladed surface; Pulled shoulders or ditches
HCR 1369	2/27/2012	Bladed surface; Added rock
HCR 1414	2/1/2012	Hauled materials for work crew hauled 6 loads of base to 1414 S
	2/1/2012	Bladed surface; Added rock
	2/1/2012	Hauled materials for work crew hauled 6 loads of base to 1414 S
	2/2/2012	Bladed surface; Added rock
	2/3/2012	Bladed surface; Added dirt
	2/6/2012	Bladed surface; Added rock graded 1414 South and North of FM 67
	2/7/2012	Hauled materials for work crew hauled 4 loads to 1414; 2 loads to 1306; 1 load to 1120
	2/8/2012	Hauled materials for work crew hauled 5 loads of base
	2/9/2012	Hauled materials for work crew hauled 5 loads of base
	2/9/2012	Hauled materials for work crew hauled 5 loads of base
	2/10/2012	Hauled materials for work crew hauled 3 loads of base to 1414 South
	2/10/2012	Hauled materials for work crew hauled 5 loads of base to 1414 South
	2/21/2012	Bladed surface; Added rock
HCR 1414 between HCR 1120 and HCR 1414	2/2/2012	Hauled materials for work crew hauled 4 loads of base to 1414 S; 2 loads to 1120
	2/3/2012	Hauled materials for work crew hauled 2 loads of base to 1120; 2 loads to 1414
HCR 1414 between HCR 1306 and HCR 1120	2/8/2012	Hauled materials for work crew hauled 3 loads to 1414; 1 load to 1120; 2 loads to 1306
HCR 1414 between HCR 1306 and HCR 1414	2/6/2012	Hauled materials for work crew HAULED 4 loads of base to 1414; 2 loads to 1306
HCR 1414 between HCR 1414 and HCR 1120	2/8/2012	Hauled materials for work crew

Daily Work History (by Work Location)

Period: 2/1/2012 - 2/29/2012

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Hill County

Precinct 1: County Roads

HCR 1414 between HCR 1414 and HCR 1120	2/8/2012	Hauled materials for work crew hauled 5 loads of base to 1414 and 1 load to 1120
HCR 1424 between HCR 1433 and HCR 1424	2/9/2012	Bladed surface; Added rock
HCR 1429	2/22/2012	Hauled materials for work crew hauled 3 loads of base
	2/22/2012	Hauled materials for work crew hauled 2 loads of base
	2/22/2012	Hauled materials for work crew hauled 1 load of base
	2/22/2012	Hauled materials for work crew hauled 1 load of base to 1429
	2/23/2012	Hauled materials for work crew hauled 6 loads of gravel
HCR 1429 between HCR 1429 and HCR 1434	2/8/2012	Bladed surface; Added rock
HCR 1439	2/7/2012	Bladed surface; Pulled shoulders or ditches Bladerd 1439 east and westy of 1414
HCR 1450 S	2/28/2012	Bladed surface; Added rock
HCR 1458	2/23/2012	Bladed surface; Added rock
	2/24/2012	Bladed surface; Added rock
	2/27/2012	Hauled materials for work crew haulerd a load of base to 1458
	2/28/2012	Hauled materials for work crew haukled 5 loads of base
	2/28/2012	Hauled materials for work crew
	2/28/2012	Hauled materials for work crew hauled 5 loads of base
	2/29/2012	Hauled materials for work crew
2/29/2012	Hauled materials for work crew	